PATENT Cole

#### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:		)		
MAKOTO SATOH ET AL.		:	Examiner: Jason Whipkey	
		:	Art Unit: 2612	
Appln. No.: 09/110,018		) :		
Filed: July 2, 1998		)		Certificate
For:	IMAGE PICKUP APPARATUS,	)		OCT 0 3 2006
	METHOD, AND STORAGE MEDIUM FOR DISPLAYING, COMPRESSING, AND ENCODING IMAGE DATA	; ) ;		of Correction
		)		
U.S. Patent No.: 7,038,724 B2		)		
Issued:	May 2, 2006	)	September 28, 2006	

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

### CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

10/02/2006 SDENBOB1 00000022 7038724 01 FC:1811 100.60 OP Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

John A. Krause

Attorney for Patentees Registration No. 24,613

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

NY\_Main 594423v1

#### UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

US 7,038,724 B2

DATED

May 2, 2006

INVENTOR(S) :

MAKOTO SATOH ET AL.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### ON THE TITLE PAGE [56] REFERENCES CITED:

U.S. Patent Documents, insert --5,043,816 8/1991 Nakano et al. ..... 348/333.01--.

#### COLUMN 1:

Line 29, "requiring the" should read --requiring of the--.

#### COLUMN 2:

Line 42, "output;" should read --output--.

#### COLUMN 3:

Line 29, "a (CD1" should read --a CCD1--.

#### COLUMN 5:

Line 57, "frames." should read --frame.--.


#### COLUMN 6:

Line 13, "facilitate" should read --facilitates--.

#### **MAILING ADDRESS OF SENDER:**

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page



## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

US 7,038,724 B2

**DATED** 

May 2, 2006

INVENTOR(S) :

MAKOTO SATOH ET AL.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 7:

Line 9, "memory 13C" should read --memory 130--;

Line 10, "such." should read --such--;

Line 53, "106 in" should read -- 106 is in--; and

Line 56, "time" should read --time:--.

#### COLUMN 10:

Line 1, "components" should read --component--.

#### COLUMN 11:

Line 62, "second resolution" should read --second-resolution--.

#### COLUMN 12:

Line 4, "first-and" should read --first- and--;

Line 15, "a" should read --an--;

Line 37, "second resolution" should read --second-resolution--; and

Line 52, "first-and" should read --first- and--.

#### COLUMN 13:

Line 10, "wits" should read --puts--.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. <u>US 7,038,724 B2</u>

No. of add'l. copies @ 30¢ per page

90% - 3 2000M



# PRINTER'S TRIM LINE

#### UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

US 7,038,724 B2

**DATED** 

May 2, 2006

INVENTOR(S) :

MAKOTO SATOH ET AL.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 14:

Line 6, "second" should read --second---.

**MAILING ADDRESS OF SENDER:** 

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

- 3 200A

No. of add'l. copies @ 30¢ per page



## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

US 7,038,724 B2

**DATED** 

May 2, 2006

INVENTOR(S) :

MAKOTO SATOH ET AL.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### ON THE TITLE PAGE [56] REFERENCES CITED:

U.S. Patent Documents, insert --5,043,816 8/1991 Nakano et al. ...... 348/333.01--.

#### COLUMN 1:

Line 29, "requiring the" should read --requiring of the--.

#### COLUMN 2:

Line 42, "output;" should read --output--.

#### COLUMN 3:

Line 29, "a (CD1" should read --a CCD1--.

#### COLUMN 5:

Line 57, "frames." should read --frame.--.

#### COLUMN 6:

Line 13, "facilitate" should read --facilitates--.

#### **MAILING ADDRESS OF SENDER:**

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

OCT - 3 2008

No. of add'l. copies @ 30¢ per page



#### UNITED STATES PATENT AND TRADEMARK OFFICE

#### **CERTIFICATE OF CORRECTION**

PATENT NO.

US 7,038,724 B2

**DATED** 

May 2, 2006

INVENTOR(S) :

MAKOTO SATOH ET AL.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 7:

Line 9, "memory 13C" should read --memory 130--;

Line 10, "such." should read --such--;

Line 53, "106 in" should read --106 is in--; and

Line 56, "time" should read --time:--.

#### COLUMN 10:

Line 1, "components" should read --component--.

#### COLUMN 11:

Line 62, "second resolution" should read --second-resolution--.

#### COLUMN 12:

Line 4, "first-and" should read --first- and--;

Line 15, "a" should read --an--;

Line 37, "second resolution" should read --second-resolution--; and

Line 52, "first-and" should read --first- and--.

#### COLUMN 13:

Line 10, "wits" should read --puts--.

#### **MAILING ADDRESS OF SENDER:**

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

1007 - 3 2000

No. of add'l. copies @ 30¢ per page



## Staple Here Conly!

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

US 7,038,724 B2

**DATED** 

May 2, 2006

INVENTOR(S) :

MAKOTO SATOH ET AL.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 14:

Line 6, "second" should read --second---.

**MAILING ADDRESS OF SENDER:** 

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

- 3 200

PATENT NO. <u>US 7,038,724 B2</u>

No. of add'l. copies @ 30¢ per page



Form PTO 1050 (Rev. 3-82) NY\_Main 594423v1